

**THE GANDHIDHAM
CHAMBER OF COMMERCE & INDUSTRY**

(M)

(ESTD. 1953)

"CHAMBER BHAVAN", Plot No. 71, Sector 8, Post Box No. 58,
GANDHIDHAM - Kachchh - 370 201.

Phone : +91-02836-220977, 220735 • Mobile : 99250 37814 • Fax : 220888

e-mail : info@gccikandla.com • Website : www.gccikandla.com

No. GCCI / 712

Date: 11.02.2019

13.02

Shri Prabhat Kumar Singh,
Project Director - PIU
National Highways Authority of India
Z-6, Ground Floor,
Near Divine Life Society Hospital,
Adipur - Kachchh

Sub: Corrective measures on National Highway No. 8A

Dear Sir,


We wish to draw your attention towards problem being faced on National Highway No. 8A patch from Sardar Patel statue to KASEZ as under.

- There is no cut-off on service road for reaching Railway Goods Yard resulting inconveniency to regular traffic leading to Railway Goods Yard. The lacking of such facility may lead to possibilities of accidents. Hence, there is an acute need to provide cut-off road from service road to Railway Goods Yard.
- It has been observed that it has become absolutely unsafe to cross the road near Sardar Patel statue to proceed further to Railway Station due to frequent traffic jam. Hence, it is need of the hour to make that point safe for vehicle as well as for the pedestrian.

In view of the above, we request you to initiate necessary corrective measures as well as to coordinate with the local agencies to improve traffic scenario at Sardar Patel statue.

Thanking you.

Yours faithfully,



Aashish Joshi
Hon. Secretary