

## THE GANDHIDHAM CHAMBER OF COMMERCE & INDUSTRY

(ESTD. 1953)

"CHAMBER BHAVAN", Plot No. 71, Sector 8, Post Box No. 58,

GANDHIDHAM - Kachchh - 370 201.

Phone: +91-02836-220977, 220735 • Mobile: 99250 37814 • Fax: 220888

e-mail: info@gccikandla.com • Website: www.gccikandla.com

No. GCCI/104

Date: 16.05.2018

The Divisional Railway Manager Ahmedabad Divisional Office, Western Railway, Near Chamunda Mata Mandir, Opp. New Swadeshi Mill, Naroda Road, Post: Saijpur Bogha, Ahmedabad – 382 345

## Sub: Upgradation of the facilities at Adipur Railway Station

Dear Sir,

We would like to bring to your kind notice the following lacunas at Adipur Railway Station in Kachchh District.

- 1. The condition of flooring of platform No.1 is deteriorating day by day. At platform No. 1 40% area is covered by Kota Stone while balance area is made-up of asphalt which is also in deteriorating conditions while some asphalt is already removed. Hence, proper Upgradation is required.
- 2. It has also been observed that toilet facilities are not maintained properly at Adipur Station and most of the time those toilets are found locked one. Needless to mention, our respected Prime Minister's movement of SWACHH BHARAT seems have no impact on SWACHH ADIPUR STATION.
- 3. There is no facility of cover shed on Platform No. 1 & 2 which should be arranged on top most priority basis.
- 4. At Adipur Railway Station bushes have grown up like anything and no arrangement is there for removing the same.
- 5. There should be direct access to platform no. 2 through foot over bridge.

In view of the above and Adipur being a junction, the redressal of above lacunas should be initiated on the top most priority & all amenities should be provided under intimation to us.

Thanking you.

Yours faithfully,

(Murlidhar Jagani)

Hon. Secretary

Copy to: The Area Railway Manager, Gandhidham – Kutch

Shri Parasmal Nahata - Member, DRUCC